

KNKT Notification**No. KNKT.26.07.09.04**

Name, Organization and contact information of person/organization submitting notification:	 Komite Nasional Keselamatan Transportasi (National Transportation Safety Committee) Ministry of Transportation Building 3rd Floor Jl. Medan Merdeka Timur No. 5 Jakarta - INDONESIA Telephone: + 62 21 847601 Facsimile: + 62 21 3517606 24-hour Call Contact +62 81212655155 Website: www.knkt.go.id Email: aviation.knkt@kemenhub.go.id	
a) for accidents the identifying abbreviation ACCID, for serious incidents SINCID, for incidents INCID;	SINCID (Serious Incident)	
b) manufacturer, model, nationality and registration marks, and serial number of the aircraft;	Manufacturer : Bell Helicopter Model : Bell 407 Nationality : Indonesia Registration : PK-ZGL Serial Number : 53455	
c) name of owner, operator and hirer, if any, of the aircraft;	Owner : PT Sayap Garuda Indah Operator : PT Sayap Garuda Indah	
d) qualification of the pilot-in-command, and nationality of the crew and passengers;	Pilot in Command qualification : CPL-H Flight crew nationality : Indonesia Passengers nationality : Canadian	
e) date and time (local time or UTC) of the occurrence;	Local Time Date : 7 July 2026 Time : About 1700 LT	UTC Date : 7 July 2026 Time : About 0900 UTC
f) last point of departure and point of intended landing of the aircraft;	Last point of departure : Benoa Heliport, Bali, Indonesia Point of intended landing: Benoa Heliport, Bali, Indonesia	
g) position of the aircraft with reference to some easily defined geographical point and latitude and longitude;	After the kite strike, the helicopter landed and parked at Benoa Heliport.	
h) number of crew and passengers; aboard, killed and seriously injured; others, killed and seriously injured;	Persons on board are 1 pilot and 6 passengers. No one was injured as result of the occurrence.	
i) description of the occurrence and the extent of damage to the aircraft so far as is known (Destroyed/Substantial/Minor/None);	The helicopter departed from Benoa Heliport for a sightseeing flight to the Viceroy area located on 08°29'39.37" S 115°16'37.45" E and returned to Benoa Heliport. During the post-flight inspection, the engineer discovered that kite strings were entangled around the swashplate area. The pilot was not aware of any contact with a kite during the flight. The pilot also reported that there had been no abnormal aircraft handling or performance indications throughout the flight.	
j) an indication to what extent the investigation will be conducted or is proposed to be delegated by the State of Occurrence;	The KNKT classified this occurrence as a Serious Incident and will conduct the investigation in accordance with the provisions of Annex 13 to the Convention on International Civil Aviation.	
k) physical characteristics of the occurrence area, as well as an indication of access difficulties or special requirements to reach the site;	The kite strike occurred near during enroute and after the occurrence the helicopter landed at Benoa Heliport. No access difficulty or special requirement to reach the heliport.	

l) identification of the originating authority and means to contact the investigator-in-charge and the accident investigation authority of the State of Occurrence at any time;	The KNKT Indonesia Telephone : + 62 21 3847601 Facsimile : + 62 21 3517606 24-hour Call Contact : + 62 81212655155 Email : aviation.knkt@kemenhub.go.id Investigator-In-Charge (IIC) Name : Elingselasri Telephone : + 62 81373500136 Email : elingselasri.knkt@gmail.com		
m) presence and description of dangerous goods on board the aircraft.	No		
Operation Type (If information is available)	Commercial Aviation	Non-Scheduled	Passenger