

KNKT Notification		No. KNKT.25.04.04.04
Name, Organization and contact information of person/organization submitting notification:	 Komite Nasional Keselamatan Transportasi (National Transportation Safety Committee) Ministry of Transportation Building 3rd Floor Jl. Medan Merdeka Timur No. 5 Jakarta - INDONESIA Telephone: + 62 21 847601 Facsimile: + 62 21 3517606 24-hour Call Contact +62 81212655155 Website: www.knkt.go.id Email: aviation.knkt@kemenhub.go.id	
a) for accidents the identifying abbreviation ACCID, for serious incidents SINCID, for incidents INCID;	ACCID (Accident)	
b) manufacturer, model, nationality and registration marks, and serial number of the aircraft;	Manufacturer : Bell Helicopter Textron Model : Bell 505 Nationality : Indonesia Registration : PK-URT Serial Number : 65164	
c) name of owner, operator and hirer, if any, of the aircraft;	Owner : Textron Financial Corporation Operator : PT National Utility Helicopter	
d) qualification of the pilot-in-command, and nationality of the crew and passengers;	Pilot in Command qualification : CPL Flight crew nationality : Indonesian Passengers nationality : None	
e) date and time (local time or UTC) of the occurrence;	Local Time Date : 22 April 2025 Time : 14:44 LT	UTC Date : 22 April 2025 Time : 07:44 UTC
f) last point of departure and point of intended landing of the aircraft;	Last point of departure : Pondok Cabe Airport Point of intended landing: Pondok Cabe Airport	
g) position of the aircraft with reference to some easily defined geographical point and latitude and longitude;	Latitude 6° 21' 22.99" S; Longitude 106 ° 54' 4.24" E	
h) number of crew and passengers; aboard, killed and seriously injured; others, killed and seriously injured;	The persons on board are 2 pilots. No one was injured in this occurrence.	
i) description of the occurrence and the extent of damage to the aircraft so far as is known (Destroyed/Substantial/Minor/None);	During the Pilot Proficiency Check, the helicopter experienced abnormal contact with the ground in the middle of Wiladatika Airstrip (Cibubur area). The helicopter was substantially damaged.	
j) an indication to what extent the investigation will be conducted or is proposed to be delegated by the State of Occurrence;	The KNKT classified this occurrence as an Accident and will conduct the investigation in accordance with the provisions of Annex 13 to the Convention on International Civil Aviation.	
k) physical characteristics of the occurrence area, as well as an indication of access difficulties or special requirements to reach the site;	The occurrence location was at Wiladatika Airstrip where the location can be reached by land and air transportation (by means of helicopter or small aircraft).	
l) identification of the originating authority and means to contact the investigator-in-charge and the accident investigation authority of the State of Occurrence at any time;	The KNKT Indonesia Telephone : + 62 21 3847601 Facsimile : + 62 21 3517606 24-hour Call Contact : + 62 81212655155 Email : aviation.knkt@kemenhub.go.id	

m) presence and description of dangerous goods on board the aircraft.	No		
Operation Type (If information is available)	Commercial Aviation	Non-Scheduled	Other: training/check
The State of Occurrence shall forward a notification of an accident or serious incident with a minimum of delay and by the most suitable and quickest means available to: a) the State of Registry; b) the State of the Operator; c) the State of Design; d) the State of Manufacture; and e) the International Civil Aviation Organization, when the aircraft involved is of a maximum mass of over 2,250 kg.			